

Z21 ■ These assemblies are ESD sensitive, ESD precautions shall be observed.  
Z22 ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.  
Z23 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.



