



Thomas Mauer

Systems and Engineering Marketing

ABSTRACT

When a design fails an IEEE Ethernet compliance test, the design layout is often the suspected cause of the failure. Before taking steps to analyze the design layout, engineers should first investigate if the latest software was installed on the IEEE compliance test equipment. Some outdated software versions cause failure of the IEEE compliance test. This application note walks engineers through the steps of validating failure scenarios.

Table of Contents

1 Introduction	1
2 IEEE Specification and How to Derive the Formula	3
3 Formula Helper to Calculate Limit	4
4 Conclusion and Summary	4
5 References	5

Trademarks

E2E™ is a trademark of Texas Instruments.
Microsoft® are registered trademarks of Microsoft Corporation.
Tektronix® is a registered trademark of Tektronix, Inc..
All trademarks are the property of their respective owners.

1 Introduction

Why is IEEE Ethernet Compliance testing important?

The IEEE 802.3 standard defines a set of compliance tests for the 1000BASE-T Ethernet physical layer. These tests are intended to ensure reliable communications over an Ethernet network. To perform this testing, the device under test (DUT) is placed in each of four IEEE 802.3 specified modes. The standard defines the test modes as listed in [Table 1-1](#).

Table 1-1. 1000BASE-T Physical Layer Compliance Standard

Test Mode	Test	IEEE 802.3 Reference
Test Mode-1	Peak Droop Template	40.6.1.2.1 40.6.1.2.2 40.6.1.2.3
Test Mode-2 Test Mode-3	Transmitter Jitter Receiver Jitter	40.6.1.2.5
Test Mode-4	Distortion MDI Return Loss MDI Common Mode Voltage	40.6.1.2.4 40.8.3.1 40.8.3.3

Ethernet compliance is executed with an oscilloscope that operates a specific Ethernet compliance software test suite. Such Ethernet compliance test equipment is made available for purchase from many test equipment manufacturers like Tektronix, Agilent, Lecroy and others.

Problem Description

Ethernet compliance test equipment implements a software test suite. The software suite executes the test cases step by step in a semi-automated way. The IEEE specification in some cases does not provide a fixed formula but describes the type of math in text form. Each test equipment vendor has the freedom to implement their own measurement ways and formulas. As result, different interpretations of the math formula have been implemented by manufacturers in their Ethernet compliance testing software suite.

Specifically, we are looking at test case “Peak differential output voltage and level accuracy” as described in IEEE 802.3-2018 Subclause 40.6.1.2.1. This test case requires Test Mode-1 to be activated in the Ethernet PHY.

What we have observed in the market is that two different kinds of formulas are implemented by test tool manufacturers. One formula calculates percentage error, while the other calculates percentage difference.

Some manufacturers implemented the percentage error formula in a different way to other manufacturers. In some cases, this resulted in a doubling of test values, and subsequently erroneous failures. [Figure 1-1](#) illustrates an example.

Summary Table

[\[Hide Table\]](#)

Pass	#	Test	Measurement	Current Value	Test Criteria
✓	1	40.6.1.2.1	Peak A (Pair A)	695.89 mV	$x = 745.00 \text{ mV} \pm 75.00 \text{ mV}$
✓	1	40.6.1.2.1	Peak B (Pair A)	708.24 mV	$x = 745.00 \text{ mV} \pm 75.00 \text{ mV}$
✗	1	40.6.1.2.1	Peak A vs Peak B (Pair A)	-1.775 %	$-1.000 \% < x < 1.000 \%$

Figure 1-1. Peak A vs Peak B Failure due to Incorrect Formula

[Figure 1-1](#) uses the wrong formula and therefore fails to pass Peak A versus Peak B test case. In some cases, the Ethernet compliance test vendors have already updated their Ethernet compliance test suite firmware with the corrected formula. The engineer performing Ethernet compliance test cases may need to update the test equipment software with the latest software version from the manufacturer. For the update the vendor of the test equipment has to be contacted.

Contact the test equipment vendor for updates. Use this application note to determine whether or not the correct formula for the Peak A versus Peak B test is used by the test equipment.

2 IEEE Specification and How to Derive the Formula

The IEEE 802.3-2018, Subclause 40.6.1.2.1 is written as follows:

"The absolute value of the peak of the waveform at points A and B, as defined in Figure 40–20, shall fall within the range of 0.67 V to 0.82 V (0.75 V ± 0.83 dB). These measurements are to be made for each pair while operating in test mode 1 and observing the differential signal output at the MDI using transmitter test fixture 1 with no intervening cable.

The absolute value of the peak of the waveforms at points A and B shall differ by less than 1% from the average of the absolute values of the peaks of the waveform at points A and B.

The absolute value of the peak of the waveform at points C and D as defined in *Figure 40–20* shall differ by less than 2% from 0.5 times the average of the absolute values of the peaks of the waveform at points A and B."

See *Figure 40–20—Example of transmitter test mode 1 waveform (1 cycle)* in the IEEE specification for further explanation of the points A and B:

The second paragraph of the specification description in section 40.6.1.2.1 contains the description of the math formula required to calculate "Peak A vs. Peak B": *The absolute value of the peak of the waveforms at point A and B shall differ by less than 1% from the average of the absolute value of the peaks of the waveform at point A and B.*

The first part of the sentence "the absolute value of the peak of waveforms at point A and B" means that each of them individual waveforms need to comply to the next part of the sentence. It also means that signs of the measurement values have to be removed and the absolute value must be used.

The second part of the sentence "... average of the peaks of the waveforms at point A and B" refers to the following percentage error formula.

The percentage error formula is defined as follows:

Percent Error Applied when comparing an experimental quantity, with a theoretical quantity, which is considered the "correct" value. The percent error is the absolute value of the difference divided by the "correct" value times 100.

$$\text{Generic formula: Percent error} = \frac{|E - T|}{|T|} \times 100\% \quad (1)$$

E is the measured value, either Peak A or Peak B.

The theoretical quantity T is defined as the average of Va and Vb, which is calculated as:

$$T = \left| \frac{V_A + V_B}{2} \right| \quad (2)$$

When Peak A absolute value is Va and Peak B absolute value is Vb, the following formula of the IEEE specification and the percent error formula can be derived:

$$\text{percent error formula} = \frac{V_B - \left| \frac{V_A + V_B}{2} \right|}{\left(\left| \frac{V_A + V_B}{2} \right| \right)} \times 100\% \quad (3)$$

3 Formula Helper to Calculate Limit

The following formula can be copied into a Microsoft® Excel file. With this helper the engineer can validate if the test equipment vendor is using the correct percent error formula:

Pass	#	Test	Measurement	Current Value
✓	1	40.6.1.2.1	Peak A (Pair A)	695.89 mV
✓	1	40.6.1.2.1	Peak B (Pair A)	708.24 mV
✗	1	40.6.1.2.1	Peak A vs Peak B (Pair A)	-1.775 %

Va = 695.89 mV

Vb = 708.24 mV

=100*((B2-0.5*(B1+B2))/(0.5*(B1+B2)))

	A	B	C
1	Peak A	695.89 mV	
2	Peak B	708.24 mV	
3	Difference A, B	0.879548 %	
4			

Figure 3-1. Formula in Microsoft® Excel

The result in the Excel table cell B3 reports that the test result has been passed because it is below 1%. The test report from the test equipment vendor shows a failed test case. In this case the formula used in [Figure 1-1](#) by the manufacturer is incorrect and out-of-date. When facing this situation, contact the test manufacturer for a software update.

4 Conclusion and Summary

This application brief provides a simple and easy method to validate if the test case passes even though the test report shows a test case failure. When the test case fails after validating the formula, further hardware analysis must be made to find the root cause of the failure. From TI experience the following can cause the Ethernet compliance test case to fail:

- *Incorrect formula* - check that the formula for the test case is correct using the formula and method described in [Section 3](#).
- *Unsupported transformer* - Validate that the transformer used in the design does match with the Ethernet PHYs transformer requirements (see the transformer section in the data sheet and compare it with transformer data sheet and schematics implementation).
- *Layout optimization* - Review the Ethernet PHY layout guidelines and recommendations in the PHY data sheet.
- *Transmission line interaction* - Cross talk impact of transmission lines by enabling transmit on signal pair only.
- *Drive strength tuning* - Some Ethernet PHYs have the capabilities to increase or decrease the transmission drive strength on the MDI interface inside the PHY. Tuning the drive strength per pair can be used to potentially pass the compliance tests.
- *Magnetics decoupling* - On the MDI side, capacitors are connected to the center taps of the transformer. Tuning the value of these capacitors may help pass the compliance tests.

Additional components on the MDI routing to Magnetics: ESD or other components with high capacitance and impedance added on the path will be evaluated.

Post Ethernet questions to the [TI E2E™ forum](#).

5 References

- Texas Instruments, [How to Configure DP838xx for Ethernet Compliance Testing Setup Application Report](#)
- Texas Instruments, [AN-1469 PHYTER Design and Layout Guide Application Report](#)
- Tektronix®, [Physical Layer Compliance Testing for 1000BASE-T Ethernet Application Note](#)

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, or other requirements. These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to TI's Terms of Sale (<https://www.ti.com/legal/termsofsale.html>) or other applicable terms available either on [ti.com](https://www.ti.com) or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265
Copyright © 2021, Texas Instruments Incorporated