

Power Validation

Step 1:

Using a bench top power supply, set the compliance to 12V and 1A accordingly. Plug the jack into the RAP722 plug on the board (item #1) and slide the switch to “JACK” (item #2).



