





VBAT



These assemblies are ESD sensitive, ESD precautions shall be observed.
These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.
These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.

- nSCS
- SCLK
- SDI
- SD0
- nSLEEP
- IN1
- IN0

LDO_3V3
VDD
MCU_3V3

VM

For evaluation only; not FCC approved for resale.

GND

3V3

GND